

PRODUCT SAFETY RECALL**HONEYWELL FALL PROTECTION FRANCE SAS RECALLS H500-SERIES HARNESSES**

Honeywell Fall Protection France SAS is recalling the Honeywell Miller branded H500 series harnesses produced between 1 March and 30 June 2025 at the Nabeul, Tunisia production facility. The affected products can be identified by their manufacturing date, article number and manufacturing location, which are indicated on the product label. The product was sold through distributors.



Above pictures show an illustrative example for each configuration of H500 Series Harnesses

The article numbers concerned are listed in the following table:

Article Number	Designation
1036081	H500 Pad QB 2D size 1
1036082	H500 Pad QB 2D size 2
1036083	H500 Pad QB 2D size 3
1036085	H500 Pad QB 2LO size 1
1036086	H500 Pad QB 2LO size 2
1036087	H500 Pad QB 2LO size 3
1036093	H500 QB size 1
1036095	H500 QB size 3
1036096	H500 MB 2D size 0
1036097	H500 MB 2D size 1
1036098	H500 MB 2D size 2
1036099	H500 MB 2D size 3
1036100	H500 QB 2D size 0

<u>1036101</u>	H500 QB 2D size 1
<u>1036105</u>	H500 QB 2LO size 0
<u>1036106</u>	H500 QB 2LO size 1
<u>1036107</u>	H500 QB 2LO size 2
<u>1036108</u>	H500 QB 2LO size 3
<u>1036109</u>	H500 QB 2LO Q-Fit size 1
<u>1036110</u>	H500 QB 2D size 2
<u>1036111</u>	H500 QB 2D size 3
<u>1036121</u>	H500 QB 2LO Q-Fit size 2
<u>1036122</u>	H500 QB 2LO Q-Fit size 3
<u>1036123</u>	H500 QB 2LO Ylow HV size 1
<u>1036124</u>	H500 QB 2LO Ylow HV size 2
<u>1036125</u>	H500 QB 2LO Ylow HV size 3
<u>1036126</u>	H500 QB 2D Ylow HV size 1
<u>1036127</u>	H500 QB 2D Ylow HV size 2
<u>1036128</u>	H500 QB 2D Ylow HV size 3
<u>1036130</u>	H500 QB 2LO Oran HV size 2
<u>1036131</u>	H500 QB 2LO Oran HV size 3
<u>1036133</u>	H500 QB 2D Oran HV size 2
<u>1036134</u>	H500 QB 2D Oran HV size 3
<u>1036591</u>	EDGE TESTED ROOFING KIT - H500
<u>1036592</u>	EDGE TESTED MAINTENANCE PSS KIT - H500
<u>1036595</u>	SCAFFOLDING PSS KIT - H500
<u>1036597</u>	SCAFFOLDING TURBOLITE PSS KIT - H500
<u>1036598</u>	H500 IC6 COMFORT HARNESS KIT - SIZE 2
<u>3007-3736-001</u>	H500 Mobile Platform KIT Size 2

WHY IS THIS PRODUCT DANGEROUS?

A limited number of units of the H500-Series Harnesses produced at the Nabeul, Tunisia facility between March 1, 2025, and June 30, 2025 may have been assembled with incorrect webbing routing through the front/sternal D-ring and/or leg buckles, posing a serious safety risk. This deviation may severely limit or even completely disable the safety function of the harness in the event of a fall from height. In specific circumstances, the front/sternal D-ring and leg buckles may not be able to withstand the necessary load requirements. This could result in serious, potentially fatal, injuries.

WHAT TO DO?

Please stop using the H500 harness that you purchased **immediately** and follow the steps below to check whether your product is potentially affected.

If your product is identified as affected, please continue to refrain from using it. In this case, we kindly ask you to contact us (contact details below). You will be informed by e-mail about the specific procedure for return.

First, locate the manufacturing label on your H500-series harness model.

Step 1: Article Number

Please check whether the Article Number indicated on your product is included in the table above.

- If the Article Number on the manufacturing label of your H500 product is not listed in the table above, the unit is compliant—no further action needed.
- If the Article Number on the manufacturing label of your H500 product is listed in the table above, proceed to Step 2



Step 2: Manufacturing location

Please check where your product was produced.

- If the label states, "Made in Slovakia," the unit is compliant—no further action is needed.
- If it states, "Made in Tunisia", please proceed to Step 3



Step 3: Manufacturing date

Please check if your product was produced between March 1, 2025, and June 30, 2025, if yes, please contact us (contact details below).

- If the manufacturing date indicated on the label of your product is outside the date range stated above, the unit is compliant—no further action is needed. You may continue to use the harness.
- If it is INSIDE the date range stated directly above —please contact us (contact details below).

**REMEDIES FOR CONSUMERS**

Honeywell Fall Protection France SAS will examine the returned products. If your harness is not affected, we will of course return it to you as quickly as possible and free of charge. If your harness is found to be affected by the safety issues described above, Honeywell Fall Protection France SAS will contact you immediately and provide one of the following remedies free of charge:

1. **Repair** of the affected harness to restore full compliance with the applicable safety and performance requirements; or
2. **Replacement** of the affected harness with a new product of the same type that meets all applicable safety and quality specifications. Contact our customer service team via e-mail (contact details below) for return shipping labels and instructions.

CONTACT

Consumers seeking further information regarding this recall may contact our customer service team via e-mail:

Countries	Customer Service Mailbox
France, French overseas departments and territories	advroissy.hspf@honeywell.com
United Kingdom, Ireland	info-uk.hsp@honeywell.com
Belgium, Luxembourg, Netherlands	info-benelux.hsp@honeywell.com
Austria, Switzerland, Germany	info-germany.hsp@honeywell.com
Italy	info-italia.hsp@honeywell.com
Sweden, Norway, Finland, Denmark, Iceland	info-nordic.hsp@honeywell.com
Poland, Slovakia, Romania, Czech Republic, Slovenia, Estonia, Croatia, Bulgaria, Latvia, Lithuania	info-poland.hsp@honeywell.com
Spain, Portugal, Greece, Cyprus, Malta	SP56SALESSPAIN@Honeywell.com
Hungary	info-hungary.hsp@honeywell.com

We sincerely apologize for any inconvenience this may cause and ask for your understanding as we take this measure in the interest of your safety.

Please inform others about this recall, especially if you know someone who has been offered, lent, or sold the recalled product.

